www.attelsr.lv

ATTĒLS R Ltd., 11 Mašīnu Str., Riga, LV-1063, e-mail: info@attelsr.lv
Board materials: phone 67846678, 67187016, e-mail platnes@attelsr.lv
Furniture fittings phone 67846682, 67844884, e-mail furnitura@attelsr.lv
Components' production: phone 67844864, 67846675, e-mail detalas@attelsr.lv
Delivery within Latvia: phone 67846676
Operating hours: Monday to Friday 8.00 - 17.00, Saturday 10:00 - 15:00, Sunday - closed

Article	Name	Unit	Color	Lenght, mm	Price EUR per unit
outgoing sale 31-RELING300-29	Gallery railing SAM BOX	kom	cream	300.0	1.08
outgoing sale 31-RELING300P	Gallery railing SAM BOX	kom	grey	300.0	1.4
outgoing sale 31-RELING350-29	Gallery railing SAM BOX	kom	cream	350.0	1.64
outgoing sale 31-RELING350P-29	Gallery railing SAM BOX	kom	grey	350.0	1.72
outgoing sale 31-RELING400-29	Gallery railing SAM BOX	kom	cream	400.0	1.3
31-RELING400P-29	Gallery railing SAM BOX	kom	grey	400.0	2.71
31-RELING450-29	Gallery railing SAM BOX	kom	cream	450.0	2.84
31-RELING450P-29	Gallery railing SAM BOX	kom	grey	450.0	3.55
31-RELING500-29	Gallery railing SAM BOX	kom	cream	500.0	3.42
31-RELING500P-29	Gallery railing SAM BOX	kom	grey	500.0	3.55
outgoing sale 31-RELING550-29	Gallery railing SAM BOX	kom	cream	550.0	2.05
31-RELING550P-29	Gallery railing SAM BOX	kom	grey	550.0	3.23
outgoing sale 31-1121992	Gallery railing adapter	gab.	cream	-	0.05
outgoing sale 31-11219921	Gallery railing adapter	gab.	cream	-	0.16
outgoing 31-127901751	Drawer inside divider H-120 mm	gab.	balta	-	0.91
outgoing 31-127901761	Drawer inside divider H-185 mm	gab.	white	-	1.03
outgoing 31-127901763	Drawer inside divider H-185 mm	gab.	grey	-	1.06
outgoing 31-127902011	Bottle holder	gab.	white	-	0.39
outgoing 31-127902013	Bottle holder	gab.	grey	-	0.39

outgoing - This article will not be available anymore. Please ask about remnants to the customer service specialists.

sale - This article has a reduced price and will not be available anymore. Please ask about remnants to the customer service specialists.

Prices excluding VAT. The indicated prices may be changed without a prior warning.