




x1



x2



x4/x5/x6



x2



x2




x1




St4x40

Ø6x30

x2





x4



1



a)





L_{Track} [mm]	1950	2400	3000
X [mm]	840	1120	1400
n [szt]	4	5	6

$$\begin{matrix} H_0 \\ L_0 \end{matrix} \Rightarrow d \text{ \& } H_1$$




b)



2




3



4

x4




x8




x1




#5



4.1



4.2




5





x2



x2




6




7


x2



#2



7a



7b

