




COMPONENTS


Monteringsanvisning Assembly Instructions Asennusohjeet Montageanleitung Monteringsvejledning

We Cherish




Pull-out Ironing Board

5200



4x




4x




4x




6x




1x





1x



1x



1x




8mm


8mm


22,5mm


9mm











1









! X=X



4








5







$$B = A - 3\text{mm}$$
$$C1 = C2$$









C O M P O N E N T S